

**FIGURE 3:**  
Root Close up. This picture was taken minutes after the natural gas supply was shut off and made safe.

This is the saw cut that breached the 2" steel natural gas line.

Approximate Natural Gas line location INSIDE the root.

