

Memorandum

April 7, 2015

To: Timothy I. Meyer, COO
From: Martha Michels *mm*
Subject: FESHM Chapter 5033.1 – Vacuum Window Safety


This is the initial release of FESHM Chapter 5033.1 – Vacuum Window Safety. Vacuum windows pose a potential hazard to equipment and personnel from rupture or implosion. This chapter specifies the procedure to be followed in designing, fabricating, testing and using vacuum windows in order to reduce hazards.

This chapter went out for lab-wide review and all comments were addressed. After Directorate approval, please return this approval page to Jody Federwitz at MS119 for posting on the web.

Encl.

Recommended for Approval:

Timothy I. Meyer, COO*4/16/15*

Date**Approved:**

Nigel S. Lockyer, Director of Fermilab*4/15/15*

Date

*Not an initial release - it was
Rev. 0 w/ no history on the Draft.
Per Martha Michels, leave as is.*

