

Martha E. Michels  
Chief Safety Officer

**ESH&Q Section**  
P.O. Box 500, MS 119  
Kirk Road and Pine Street  
Batavia, Illinois 60510-5011  
USA  
Office: 630.840.3511  
[martha@fnal.gov](mailto:martha@fnal.gov)

**Date:** July 23, 2018  
**To:** file  
**From:** Martha Michels   
**Re:** FESHM Chapter 4230 – Confined Spaces

---

Rich Ruthe added a NOTE to Section 4.2, Permit-Required Confined Space Entry Procedures, of the FESHM chapter on confined spaces to warn of the interference by helium of the oxygen sensor on the MSA Altair 5X. This information was just provided by MSA. The note also includes a requirement to use the MSA Altair ProR oxygen meter, which is available from the IH Group, in instances where there could be a helium interference.

An informational email will be sent, via TRAIN, to people that have attended the confined space training sessions to alert them to the change. There is no need to alter the confined space entry forms or the training modules according to the Subject Matter Experts.

This chapter did not go out for lab-wide review and does not require Directorate approval.

Encl.