



Nancy L. Grossman  
Section Office  
ESH&Q Section  
630.840.3810 (phone)  
630.840.3390 (fax)

DIRECTOR'S OFFICE  
MAR 18 2013

## Memorandum

March 18, 2013

**To:** Jack Anderson  
**From:** Nancy Grossman *NG*  
**Subject:** Revised FESHM Chapter 5120 – Fermilab Energy Control Program  
(Lockout / Tagout)

FESHM Chapter 5120 has been updated as follows:

- Section 11, General LOTO Procedure, clarified the verification step by adding “the proper level of PPE shall be worn until zero voltage verification is assured.”

This chapter was reviewed by subject matter experts. After Directorate approval, please return this approval page to Jody Federwitz at MS119 for posting on the web.

Encl.

### Recommended for Approval:

*Jack Anderson*  
\_\_\_\_\_  
Jack Anderson

*4/9/13*  
\_\_\_\_\_  
Date

### Approved:

*Piermaria Oddone*  
\_\_\_\_\_  
Piermaria Oddone

*4/9/13*  
\_\_\_\_\_  
Date