

**FIGURE 1:**  
Dorm 4 pre-excavation.

Natural Gas utility clearly marked, both flagged and painted by ATS (locating contractor).

Sanitary Sewer marked, both flagged and painted by ATS (locating contractor). Additionally, location of "BLOCKAGE" is sprayed on the ground where it has been identified (by ATS).

Proposed  
Excavation Area.

